

midwest.hse.ie

Limerick V94 AY27

Email: pqmidwestacute@hse.ie



FFS Meàn Iarthair 31/32 Sráid Chaitríona, Luimneach V94 AY27

IC/JC/MC

2nd April 2025

Deputy Joe Cooney, Dàil Eireann, Leinster House, Kildare Street, Dublin 2

PQ 10291/25

Dear Deputy Cooney

I refer to your correspondence dated 4th March 2025.

Table outlines radiology equipment in place at University Hospital Limerick, I can confirm that all machines are in working order:

Madiality	Number of		Location
Modiality	systems		Location
			CT 1 Main Department
			CT 2 Main Department
CT		3	CT Emergency Dept
MRI		2	MRI 1 MRI 2
X-ray		5	X-ray Main Department (2 Rooms) X-Ray AFU X-ray Emergency Department (2 Rooms)
Ultrasound		3	Main Department

I trust this clarifies the position. Please contact me if you have any further queries.

Kind Regards,

IAN CARTER CEO Mid West Acute and Older People Services HSE Mid West